Date Inspected: 3/4/2011

Inspected By: Brett Gilmore/ Robert Bloxham

GATES	EXERCISED	FLAP	COMMENTS
			ALL SLIDE GATES OPENED COMPLETELY PER WILLIAMS ENGINEERING
			all flap gates excavated except c11
C-1		x	
C-3			filled with slurry and abondoned due to subdivision
C-5	xx	xx	Dual slide and flap gate
C-7		x	
C-9		x	
C-11		x	
C-13		x	
C-15		x	
C-17		x	
C-19		x	
C-21		x	
C-23		x	
C-25	xx	xx	dual slide and flap gate
C-27		x	
C-29		x	
C-31		x	
C-33		x	
C-35		x	

Date Inspected: 3/4/2011

Inspected By: Brett Gilmore/ Robert Bloxham

GATES	EXERCISED	FLAP	COMMENTS
C-2		x	inlet needs minor excavation
C-4			inlet needs minor excavation
C-6			ok
C-8			ok
C-10		x	
C-12		x	
C-14		x	
C-16		x	
C-18		x	storm sewer outlet from Ross Park/S. 5th
C-20	x	x	
C-22		x	
C-24		x	
C-26		x	
C-28		x	minor inlet obstruction
C-30		x	minor inlet obstruction
C-32		x	
C-34		x	
C-36		x	
C-38		x	
C-40		x	
C-42		x	
C-44		x	
C-46		x	
C-48	x		Second Street wetlands outlet